



« 1992 Mustang Table of Contents »

«Group 01: BODY»

«Section 01-20B: Restraints, Passive--Supplemental Air Bag System»

«DIAGNOSIS AND TESTING»

Print Diagnostic Routine

---

**PINPOINT TEST O: FAULT INDICATION--AIR BAG INDICATOR FLASHES FAULT CODE 45--PROBABLE FAULT--CENTER FRONT CRASH SENSOR NOT MOUNTED TO VEHICLE PROPERLY**

---

**O3      VERIFY CENTER FRONT CRASH SENSOR**

---

- Remove center front crash sensor from vehicle.
- Clean crash sensor bracket and vehicle mounting surfaces.
- Install sensor.
- Measure resistance from center front crash sensor connector Circuit 622 (P/LG) to ground.
- **Is resistance less than 2 ohms?**

**Yes**

RECONNECT system. VERIFY system. REACTIVATE system.

**No**

REPLACE center front crash sensor. RECONNECT system. VERIFY system. REACTIVATE system.

---